

## field and playground master plan - soldiers point public school



### A Vegetable Garden

Existing vegetable garden with retaining wall to make level

### B Sloped lawn under trees

- Existing trees with benches and picnic tables under
- excessive wear has removed grass from under trees
- tree roots are impacted from soil compaction

Existing aluminium benches and picnic tables

### C Play Field

Field is waterlogged for extended periods due to ineffective drainage

Wooden retaining wall needs replacement

### D Lawn by COLA

- Excessive wear from foot traffic across lawn
- grass has been worn away
- soil compaction will damage tree health

Existing picnic tables and benches along wall

### E Hillside Play

Vegetation is receding due to foot traffic and play activities

Erosion needs addressing

### F Playground

- Proposed playground area
- mature trees to be removed
- large level changes
- phased construction with removal of library



Scale: NTS